



MUFA EF PE100 SDR11

Diametru (mm)	Timp sudare (sec)	Timp racire (min)	Cod
25	25	10	ME 25
32	50	10	ME 32
40	40	10	ME 40
50	70	10	ME 50
63	130	10	ME 63
75	70	15	ME 75
90	110	15	ME 90
110	170	15	ME 110
125	200	10	ME 125
140	250	30	ME 140
160	330	30	ME 160
180	360	20	ME 180
200	440	20	ME 200
225	600	30	ME 225
250	600	30	ME250
280	600	30	ME280
315	900	30	ME315
355	900	30	ME 350
400	920	30	ME 400




REDUCTII EF PE 100 SDR 11

Diametru (mm)	Timp sudura (sec)	Timp racire (min)	Cod
32x25	35	10	RE 32x25
40x32	40	10	RE 40x32
50x32	50	10	RE 50x32
50x40	50	10	RE 50x40
63x32	80	10	RE 63x32
63x40	100	10	RE 63x40
63x50	100	10	RE 63x50
75x63	60	15	RE 75x63
90x63	65	15	RE 90x63
90x75	90	15	RE 90x75
110x63	90	15	RE110x63
110x75	130	15	RE110x75
110x90	140	15	RE110x90
125x90	90	10	RE125x90




CAPAC EF PE100 SDR11

Diametru (mm)	Timp sudare (sec)	Timp racire (min)	Cod
25	25	10	ZE 25
32	50	10	ZE 32
40	40	10	ZE 40
50	70	10	ZE 50
63	130	10	ZE 63
75	70	15	ZE 75
90	110	15	ZE 90
110	170	15	ZE 110
125	220	20	ZE125
140	220	20	ZE140
160	330	30	ZE 160
180	350	30	ZE180
200	350	30	ZE200




COT 45° EF PE100 SDR11

Diametru (mm)	Timp sudura (sec)	Timp racire (min)	Cod
25	35	3	KE25x45
32	50	10	KE 32x45
40	40	10	KE 40x45
50	70	10	KE 50x45
63	130	10	KE 63x45
75	120	10	KE 75x45
90	110	15	KE 90x45
110	180	15	KE110x45
125	200	15	KE125x45
160	200	15	KE160x45
180	300	20	KE180x45




COT 90° EF PE100 SDR11

Diametru (mm)	Timp sudura (sec)	Timp racire (min)	Cod
32	50	10	KE 32x90
40	40	10	KE 40x90
50	70	10	KE 50x90
63	130	10	KE 63x90
75	120	10	KE 75x90
90	110	15	KE 90x90
110	180	15	KE110x90
125	200	15	KE125x90
160	200	15	KE160x90
180	300	20	KE180x90




TEU EGAL EF PE100 SDR11

Diametru (mm)	Timp sudura (sec)	Timp racire (min)	Cod
25	27	10	TE25
32	50	10	TE32
40	40	10	TE40
50	70	10	TE50
63	130	10	TE63
75	131	15	TE75
90	131	15	TE90
110	200	20	TE110
125	220	20	TE125




TEU REDUS EF PE100 SDR11

Diametru (mm)	Timp sudura (sec)	Timp racire (min)	Cod
32x25	50	10	TE32x25
40x25	40	10	TE40x25
40x32	40	10	TE40x32
50x32	70	10	TE50x32
50x40	70	10	TE50x40
63x32	130	10	TE63x32
63x40	130	10	TE63x40
63x50	130	10	TE63x50
90x63	135	15	TE90x63
110x63	135	15	TE110x63



SA BRANSARE EF PE100 SDR11 cu colier

Diametru (mm)	Timp sudura (sec)	Timp racire (min)	Cod
63/32	90	15	OE63/32
75/32	90	15	OE75/32
90/32	90	15	OE90/32
110/32	90	15	OE110/32
160/32	90	15	OE160/32
63x63	80	15	OE63x63
75x63	80	15	OE75x63
90x63	100	15	OE90x63
110x63	100	15	OE110x63
140x63	100	15	OE140x63
160/63	100	15	OE160x63
180x63	100	15	OE180x63
200x63	100	15	OE200x63
225x63	100	15	OE225x63
250x63	100	15	OE250x63
280x63	100	15	OE280x63
315x63	100	15	OE315x63





355x63	100	15	OE355x63
90x90	150	10	OE90x90
110x90	150	10	OE110x90
125x90	150	10	OE125x90
160x90	170	10	OE160x90
180x90	170	10	OE180x90
200x90	170	10	OE200x90
225x90	210	14	OE225x90
250x90	210	14	OE250x90
125x110	240	16	OE125x110
160x110	240	16	OE160x110
180x110	240	16	OE180x110

TEU BRANSARE EF PE100 SDR11 cu colier

Diametru (mm)				
40x25	225x25	200x32	225x40	63x63
50x25	40x32	225x32	63x50	75x63
63x25	50x32	63x40	75x50	90x63
75x25	63/32	75x40	90x50	110x63
90x25	75x32	90x40	110x50	125x63
110x25	90/32	110x40	125x50	140x63
125x25	110/32	125x40	140x50	160x63
140x25	125x32	140x40	160x50	180x63
160x25	140x32	160x40	180x50	200x63
180x25	160x32	180x40	200x50	225x63
200x25	180x32	200x40	225x50	

